d his

(FILE 'HOME' ENTERED AT 17:26:34 ON 14 DEC 2001)

FILE 'REGISTRY' ENTERED AT 17:28:56 ON 14 DEC 2001

L10 (.1<SN<1 AND .1<AG<1 AND 2<FE<3 AND 0<ZN<.5 AND 0<P<.2 AND 0<CR 3 (.1<SN<1 AND .1<AG<1 AND 2<FE<3 AND 0<ZN<1 AND 0<MG<1 AND 50<CU L2

FILE 'HCAPLUS' ENTERED AT 17:31:29 ON 14 DEC 2001

L3 3 L2

FILE 'REGISTRY' ENTERED AT 17:33:47 ON 14 DEC 2001 L484 (1<FE<3 AND 0<ZN<1 AND 0<P<.5 AND 50<CU)/MAC

FILE 'HCAPLUS' ENTERED AT 17:34:43 ON 14 DEC 2001

L5 271 L4

L6 22347 (COPPER OR CU) AND (ZINC OR ZN) AND (PHOS? OR P) AND (IRON OR F L7

61 L5 AND L6

968 TENSILE? AND IACS

SELECT L3 IPC 2

93581 E1-4 L9

728 L9 AND L8 L10

FILE 'REGISTRY' ENTERED AT 17:36:37 ON 14 DEC 2001

L11 39119 (50<CU)/MAC

FILE 'HCAPLUS' ENTERED AT 17:36:56 ON 14 DEC 2001

488 L11 AND L10 L12

487 L12 AND (COPPER OR CU) L13

L14 99817 HIGH(2A) ELECTR?

L15 170 L13 AND L14